


MURRAY COUNTY.

Section 35

10798 McGill-Warner Co., Blank Book Manufacturers, St. Paul.

Township 107

Range 40



"C" Concrete Stone: R.P. Tack in cor fence post SW. 45°: R.P.

Tack in cor. fence post SE. 52.5'

"D" Concrete Stone: R.P. Tack in fence post NW. 67.5': R.P.

Tack in fence post NE. 46°

"D" Conc. Block with a + on top - 6" below road top, found August 5, 1969 - R.P. Spike in P.P. 54.7' S.E.
 Monument on Line with Fence Line South. R.P. Spike in T.P. 69.9' N.E.

"G" Conc. Block with a + on top - 6" below road top, found August 5, 1969 -

34
35
36