

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST QUARTER Corner of Section 11, Township 108, Range 40, 5TH P.M.

STATE OF MINNESOTA, County of MURRAY


At the corner location shown on the sketch:

On \_\_\_\_\_ found a \_\_\_\_\_  
DATE

left monument as found,  lowered monument,  removed monument (explain)

On AUG. 29, 2008 placed a 1 INCH IRON PIPE  
DATE

### SKETCH OF REFERENCE TIES



Minnesota State Plane Coordinate  
System MURRAY County Datum  
NAD83 (1996)  
N: 218950.582  
E: 543054.001

NAIL AND SEAL IN CORNER FENCE POST WEST 39.55'

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

*Samuel Butler* 10/15/08  
SIGNATURE DATE

Registration No. 43844

- Land Surveyor,  Professional Engineer  
 County Surveyor,  County Engineer

OFFICE OF THE COUNTY RECORDER  
County of \_\_\_\_\_

I hereby certify that this document was filed in the Co. Recorders office at \_\_\_\_\_ .M on the \_\_\_\_\_ day of \_\_\_\_\_ A.D. 20 \_\_\_\_\_

County Recorder *James V. Johnson*  
By OCT 22 2008, Deputy

DOCUMENT NO. \_\_\_\_\_

Statement of Evidence

Nothing previously recorded.

On August 29, 2008 Bueltel-Moseng Land Surveying dug with a backhoe to natural ground and found nothing. We set a 1 inch iron pipe with seal #43844 in line with the fence to the west and in the centerline of the road.