Corners to be Indexed W1/4 COR. SEC. 13-108-42 E1/4 COR. SEC. 14-108-42 SW COR. SEC. 13-108-42 NE COR. SEC. 23-108-42 I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. Daniel L. Bueltel License No. 43844		JAN 2 4 2022 Karen Brann			
CERTIFICATE OF LOCATION OF GOVERNMENT CORNER Land survey monuments situated in Section 13 ,Township 108 ,Range 42 ,5TH P.M. STATE OF MINNESOTA, County of MURRAY					
FOUND MONUMENT	2634.60' 2640.13' S 83.5	SECTION	N 89'40'13" W	2637.96'	SECTION 1 108 41 SECTION 1 108 41 N: 216381.976 E: 485106.202 1" IRON N: 213744.065 E: 485122.794 5/8" IRON W/SEAL #43844 LANGE SECTION 18 108 41 LANGE SECTION 18 108 108 108 108 108 108 108 108 108
N: 211137.660 E: 479807.496 23-108-42 23-10N SECTION Murray County Coordinate System (1996 Ac	264	16'56" W 14.93' N: 2111 E: 4824 STEEL POST	52.408		N: 211106.106 E: 485118.386 CONCRETE MONUMENT 9-108-41

Statement of Evidence: SECTION 13-108-42

W1/4 COR. SEC. 13-108-42 (E1/4 COR. 14-108-42)

On June 1, 1951 a stone marked with an "X" in the top was placed at the corner.

(No Date) County plans show a stone marked with an "X" on top at the corner.

On December 12, 2021 Bueltel-Moseng Land Surveying was unable to dig for stone due to county tile running in the road. Set 5/8" iron with seal #43844 using stationing from county plans. Corner is in the center line of road and in line with occupation line to the west.

SW COR. SEC. 13-108-42 (NE COR. 23-108-42)

On June 1, 1951 a 6" round concrete monument marked with an "X" was placed at the corner.

On August 11, 1981 a concrete monument was located 2'± below the road surface. Steel fence post set above monument.

On August 11, 2015, Murray County Highway Department found a steel fence post. N: 211137.66 E:479807.496 (1996 Adj.)

On December 12, 2021 Bueltel-Moseng Land Surveying found nothing at the corner. Set a 5/8" iron with seal #43844 recorded coordinates from 2015.