

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST QUARTER Corner of Section 2, Township 105 N, Range 39 W, 5th P.M.

STATE OF MINNESOTA, County of MURRAY


At the corner location shown on the sketch:

On 10-9-75 found a 3/4" IRON ROD, FLUSH
DATE

left monument as found, lowered monument, removed monument (explain)

On _____ placed a _____
DATE

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

J. B. M. 3-21-85
G-158

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Bruce W. Sheppard
SIGNATURE

12/20/85
DATE

Registration No. 17003

Land Surveyor, Professional Engineer

County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the Co. Recorders office at _____ .M. on the _____ day of _____ A.D., 19 _____

County Recorder _____

By _____, Deputy

DOCUMENT NO. _____

East Quarter Corner Section 2, Township 105 North, Range 39 West

This corner was originally established by the U. S. General Land Office survey in 1861. The government notes show:

set post, drove charred stake, made mound with trench and pits as per instructions.

In October 1975, the DNR Bureau of Engineering contacted the following for corner information:

Murray County Offices of the Recorder and Highway Engineer
Sioux Engineering of Windom

The following information was obtained from the County Recorder's Office: A Surveyor's Record Book contains a survey done by F. A. March, date not indicated. Survey shows a stone at corner with the following ties:

reference point - northwest corner of bridge, north end, 77.2 feet
reference point - northeast corner of bridge rail, north end

A Surveyor's Record Book contains a survey done in 1936, surveyor not indicated. Survey shows that a stone was found at corner. A concrete stone was set to mark corner. The following ties are shown:

northeast corner of bridge rail, 77.2 feet
northwest corner of bridge rail, 77.2 feet
hub, southeast of stone, 50.0 feet

The following information was obtained from the County Highway Engineer's Office:

A book of field notes dated 1967 show that a concrete monument was found at corner and a 3/4" iron pin was set in its location. The following ties are shown:

reference point - "X" on north end of bridge abutment, southeast, 61.2 feet
reference point - nail and cap in power pole, southwest, 66.0 feet
reference point - "X" on north end of bridge abutment, southwest, 61.3 feet

In October 1975, the DNR Bureau of Engineering visited the area of the corner and found a 3/4" diameter iron rod. Searched for and found record ties as shown.

Accept the iron rod as the location of the corner.

Traverse information is available from the DNR Bureau of Engineering.

75hab