

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 10, Township 107, Range 43, 5TH P.M.

STATE OF MINNESOTA, County of MURRAY


At the corner location shown on the sketch:

On _____ found a _____
DATE

left monument as found, lowered monument, removed monument (explain)

On 03-03-2006 placed a 1" IRON PIPE WITH SEAL #43844 (SEE BACK)
DATE

SKETCH OF REFERENCE TIES



Minnesota State Plane Coordinate
System Murray County Datum
NAD83 (1996)

N: 190163.381
E: 440326.788

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

James V. Johnson 3/8/06
SIGNATURE DATE

Registration No. 43844

- Land Surveyor, Professional Engineer
 County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER
County of _____

I hereby certify that this document was filed in the Co. Recorders office at _____ .M on the _____ day of MAR 14 2006 A.D. 20 _____

County Recorder *James V. Johnson*
By _____, Deputy

DOCUMENT NO. _____

Statement of Evidence

In 1866, J. W. Bishop did the original subdivision of the township.

In April, 1968 the DNR assumed the fence to the north and the centerline of the road for the North Quarter corner of Section 10-107-43. This fence runs at an angle to the northwest. Midway is $60' \pm$ west of the fence to the north.

On March 3, 2006 Buettel-Moseng Land Surveying shot the North Quarter corner of Section 3, then staked out the north-south quarter line using the calculated midway. We then drove to the center of Section 3 and the north-south fence at the center of the section was $\pm 2'$. We set a 1" iron pipe with seal #43844 midway between the section corners and in the centerline of the road.