Index	No	
IIIUUCA	I V O,	
		the same of the sa

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER				
NORTH 1/4 Corner of Section 20, Township 105, Range 42, 5TH P.M.				
STATE OF MINNESOTA, County ofMURRAY At the corner location shown on the sketch :				
On 3/13/2006 found REBAR WITH AN UNREADABLE CAP IN GRAVEL				
ROAD, OPPOSITE FENCE LINE RUNNING NORTH. Ieft monument as found, lowered monument, removed monument (explain)				
On set				
Sketch of reference ties				
WOOD FENCE POST W/NAILS "X" ON TOP	FIELD			
-N-				
.8.2	· · · · · · · · · · · · · · · · · · ·			
	31st STREET			
	(GRAVEL) DUND CAPPED BAR			
N88*19'37"W, 2645.95' S8				
POWER POLE W/NAILS "X" ON SIDE				
N: 659,277.32 E: 2,120,078.65				
MN SOUTH, NAD 83				
NOT TO SCALE				
Statement of evidence relative to this corner location is on back page				
I hereby certify that this document and the dota OFFICE OF THE COUNTY RECORDS				
contained herein was prepared by me or under my direct supervision.	SEP 2 8 2006			
Land 13M	I hereby certify that this document was filed in			
Thomas V	the Co. Recorders office atM. on the day of A.D. , 20			
Registration No. 44563 X Land Surveyor, Professional Engineer	County Recorder amus V. Johnson By, Deputy			
County Surveyor, County Engineer	DOCUMENT NO.			

ſ

STATEMENT OF EVIDENCE:

1 1 1

NORTH 1/4 CORNER, SECTION 20, T. 105 N., R. 42 W.,

MURRAY COUNTY, MINNESOTA

D.W. Wellman & S.S. Smoot, US. Deputy Surveyors, monumented corner.

11/9/1912 Murray Co. found a large gray stone on corner; "unclear" tie info.

4/2/1999 Zieske Land Surveying, Inc., Perry Zieske, RLS, set a 1" iron pipe on corner.
Tie: 2636.59' to center of section .

3/13/2006 Ulteig Engineers, Inc., Survey Crew, Brain Payne Party Chief, found a rebar with an unreadable cap.

a rebar with an unreadable cap.
Ties: N-37.81' to nailed "X" on wood fence post;
S-31.8' to nailed "X" on power pole;
E-2655.03' to NE corner, Section 20;
W-2645.95' to NW corner, Section 20.