CERTIFICATE OF LOCATION O	OF GOVERNMENT CORNER
NORTHEAST Corner of Section 13 , Township 108 , Range 42 , 5TH P.M.	
STATE OF MINNESOTA, County of MURRAY	
At the corner location shown on the sketch:	
☑ On 06-13-2008 found a 1" SOLID IRON	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
Onplaced a	
, SKETCH OF REFERENCE TIES	
X X X X X 34.30'	
¥ 34.30'	
مُر	
ΔΧ΄ 55.75'	
Minnesota State Plane Coordinate	
System Murray County Datum NAD83 (1996) Nail and seal in pedestal guard post SW 55.75' E: 485106.172	
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data OFFICE OF THE COUNTY RECORDER	
contained herein was prepared by me or under	County of
my direct supervision. 1/29/09	I hereby certify that this document was filed in the Co. Recorders office atM on the day of A.D. 20
Registration No. 43844	County Recorder James V. Johnson
⊠Land Surveyor, □ Professional Engineer □ County Surveyor, □ County Engineer	DOCUMENT NO. JUL 1 0 2009 , Deputy

Statement of Evidence

In 1861, J. W. Meyers did the original survey of the east line of the township.

On June 13, 2008, Bueltel-Moseng Land Surveying found a 1" solid iron 8" below the road surface. We accepted the corner.