CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER
NORTHEAST Corner of Section 14 ,Township 108 ,Range 40 ,5TH P.M.	
STATE OF MINNESOTA, County of MURRAY	
At the corner location shown on the sketch:	
□ On found a	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
X On AUG. 29, 2008 placed a 1 INCH PIPE WITH SEAL #43844	
On AUG. 29, 2008 placed a 1 INCH PIPE WITH SEAL #43844	
SKETCH OF REFERENCE TIES	
FEEG.	DITCH
44.94', A	
Minnesota State Plane Coordinate System MURRAY County Datum NAD83 (1996)	
N: 216297.143 NAIL AND SEAL IN TELEPHONE PEDESTAL GUARD POST SW 44.94' E: 543054.948	
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.	OFFICE OF THE COUNTY RECORDER County of I hereby certify that this document was filed in
Samus But 16/15/08	the Co. Recorders office atM on the day of A.D. 20
Registration No. <u>43844</u> ☑ Land Surveyor, ☐ Professional Engineer	County Recorder James V. Johnson  By OCT 22 2008 , Deputy
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO.

## Statement of Evidence

On August 29, 2008 Bueltel-Moseng Land Surveying dug with a backhoe and found nothing. We set a 1 inch pipe with seal #43844 in the centerline of the road to the north and south and by projection line from the southeast corner (stone) through the south quarter corner (bolt over stone). We think the stone may have been taken out during the construction of the existing drainage ditch.