CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
NORTHEAST Corner of Section 19 , Township 105N ,Range 42W , 5th P.M.	
STATE OF MINNESOTA, County ofMURRAY	
At the corner location shown on the sketch:	
☑ On 2-13-08 found a 1/2" REBAR DOWN 0.8' BELOW GRAVEL SURFACE AT ROAD INTERSECTION	
□ On placed a	
SKETCH OF REFERENCE TIES	
W DE TILLED FIELD U.S.G.S MON. F230 NO SCALE PK NAIL ON SE FACE OF POWER POLE DOWN	TILLED FIELD ROAD PK NAIL ON N. FACE OF POWER POLE
MONUMENT INPLACE TILLED FIELD MONUMENT SET	_MURRAY CO. COORDINATES_
NO OTHER TIES AVAILABLE BEARING SYSTEM IS BASED ON MURRAY COUNTY COORDINATES	
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. 2-26-08 SURVEYOR'S NAME DATE	OFFICE OF THE COUNTY RECORDER County of
Registration No. 40827	County Recorder James V. Johnson
□ Land Surveyor,□ Professional Engineer□ County Surveyor,□ County Engineer	DOCUMENT NO. MAR 1 8 2008
☐ County Surveyor, ☐ County Engineer	

STATEMENT OF EVIDENCE:

NORTHEAST CORNER, SECTION 19, T. 105 N., R. 42 W.,

MURRAY COUNTY, MINNESOTA

D.W. Wellman & S.S. Smoot, U.S. Deputy Surveyors, monumented corner.

Ulteig Engineers, Inc., Survey Crew, Bob Kohler Party Chief, found a ½" rebar down 0.8' below gravel surface at road intersection.

Ties: NW-47.97' to an existing U.S.G.S. monument F230; SW-130.79' to a set PK-nail on southeast face of power pole; SE-111.19' to a set PK-nail on north face of power pole.