

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 28, Township 107, Range 41, 5TH P.M.

STATE OF MINNESOTA, County of MURRAY


At the corner location shown on the sketch:

On _____ found a _____
DATE

left monument as found, lowered monument, removed monument (explain)

On 08-02-2010 placed a 1" PIPE WITH SEAL #43844
DATE

SKETCH OF REFERENCE TIES



Minnesota State Plane Coordinate
System Murray County Datum
NAD83 (1996)
N: 174028.155
E: 500810.584

Nail and survey marker in corner fence post South 34.30'
Nail and survey marker in utility pole NW 48.35'

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.


SIGNATURE

1/12/11
DATE

Registration No. 43844

Land Surveyor, Professional Engineer
 County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER
County of _____

I hereby certify that this document was filed in the Co. Recorders office at _____ .M on the _____ day of JAN 18 2011 A.D. 20____

County Recorder James V. Johnson
By _____, Deputy

DOCUMENT NO. _____

Statement of Evidence

In 1861, L.G.M. Fletcher did the original subdivision of the township.

In 1940, a concrete stone was recorded at the corner with ties as follow:

Edge steel post NE 47.7'

Corner post South 34.3'

On August 2, 2010, Bueltel-Moseng Land Surveying dug by hand and found nothing. We set a 1" pipe with seal #43844 using the previous tie of 34.3' from the corner fence post to the south and in line with the fence to the south. The corner fell 2.5'± south of the centerline of the road.