



## Statement of Evidence

In 1866, J.W. Bishop did the original subdivision of the township.

No Date, F.R. March recorded a concrete stone at the corner with ties.

On March 21, 1973, Murray County Highway Department found a concrete monument at the corner. They place an steel pin above monument.

On May 5, 1993, Murray County Highway Department two inch long steel pin at the corner. They tied out the corner.

On June 4, 2015, Bueltel-Moseng Land Surveying found the steel pin ties to the southwest and southeast from 1993. We set a survey spike with seal #43844 by using these ties.