Index	No.	

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER	
NORTHEAST Corner of Section 5, To	ownship <u>105N</u> , Range <u>42W</u> , <u>5TH</u> P.M.	
STATE OF MINNESOTA, County of	MURRAY	
At the corner location shown on the st	ketch :	
☐ On 3/21/2006 found A 1/2" REBAR AT INTERSCETION OF		
GRA¹	VEL ROADS. wered monument, ☐ removed monument (explain)	
	Company	
Sketch of reference ties		
80th AVE.	FIELD	
5	NAOD ELVO DOCT	
-N-	WOOD FENCE POST W/PK NAIL ON SIDE x x x x x x x x x x x x x x x x x x x	
FIELD		
50,9' FOUND 1	/2 REBAR	
POWERPOLE, WITH NAILED DISC ON SIDE	GRAVEL ROAD	
C.A.S.		
	WOOD FENCE POST W/PK NAIL ON SIDE	
. 28 ROAD	FIELD N: 674,916.74	
C.S.A.H. 28	E: 2,123,212.44	
. 5	MN SOUTH ZONE, NAD 83 NOT TO SCALE	
Statement of evidence relative to this corner location is on back page		
I hereby certify that this document and the data contained herein was prepared by me or under	OFFICE OF THE COUNTY RECORDER County of	
my direct supervision.	SEP 2 8 2006	
Par 13 M	! hereby certify that this document was filed in	
	the Co. Recorders office atM. on the day of A.D. , 20	
Registration No. 44563 Professional Engineer	County Recorder, ames V Johnson, Deputy	
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO.	

STATEMENT OF EVIDENCE:

NORTHEAST CORNER, SECTION 5, T. 105 N., R. 42 W., MURRAY COUNTY, MINNESOTA

1861

D.H. Wellman & S.S. Smoot, US. Deputy Surveyors, monumented corner.

? Date:

Murray Co. found stone.

Ties: SE-44.4' to tack in fence post corner; NE-46.0' to tack in fence post corner; W-32.6' to tack in fence post, on line.

3/21/2006 Ulteig Engineers, Inc., Survey Crew, Dennis Lavallie Party Chief,

found a 1/2" rebar in the C/L intersection of the gravel roads. Ties: NE-67.7' to PK nail NE face of fence post; SE-64.5' to PK nail in SE face of fence post; W-50.9' to nail & disc in W face of power pole.