Index No.	

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
SOUTHWEST Corner of Section 29, Township 105, Range 42, 5TH P.M.		
STATE OF MINNESOTA, County ofMURRAY		
At the corner location shown on the sketch :		
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)		
	REBAR WITH CAP: RLS 44563 @ ECTION OF GRAVEL ROADS.	
Sketch of reference ties		
-N- ELECTRICAL TOP CORNER BOX TOP CORNER BOX 11th STREET	GRAVEL ROAD	
11th STREET	11th STREET	
SET CAPPED REBAR W/RLS 44563 GRAVEL ROAD	S86°27'56"E, 2679.39' GRAVEL ROAD	
	TELEPHONE PEDESTAL TP MEASURED FROM TOP CENTER OF BOX	
N: 648,836.05 E:2,117,152.88 MN SOUTH ZONE, NAD 83		
Statement of evidence relative to this corner location is on back page		
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. OFFICE OF THE COUNTY RECOF County of SEP 2 8 2006		
Thomas V: Zeff Date Registration No. 44563 Land Surveyor, Professional Engineer County Surveyor, County Engineer	I hereby certify that this document was filed in the Co. Recorders office atM. on the day ofA.D. , 20 County RecorderDeputy DOCUMENT NO	

STATEMENT OF EVIDENCE:

SOUTHWEST CORNER, SECTION 29, T. 105 N., R. 42 W., MURRAY ___ COUNTY, MINNESOTA

1861

D.W.Wellman & S.S.Smoot, US. Deputy Surveyors, monumented corner.

3/9/2006

Ulteig Engineers, Inc., Survey Crew, Brain Payne Party Chief, found nothing. Set a 5/8" rebar with cap: RLS 44563 @ intersection of gravel roads.

Ties: NW-54.1' to nailed "X" on side of power pole;

NW-47.2' to top, NE corner of electrical transformer box;

SE-62.4' to top, center, telephone pedestal;

N-2639.29' to West 1/4 corner, Section 29;

E-2679.39' to South 1/4 corner, Section 29;