


2
3

SURVEYOR'S RECORD

Range 41

Section 2

Township 105



"D" $\frac{3}{4}$ " Iron Pipe - R.P. N.40. in C.F.P. 57.73' SE, N.40. in R.P. 52.87' SW, N.40. in T.P. 56.53' N.E.
N.40. in R.P. 52.18' W.S.W.

"E" Found large Fieldstone 18" below roadtop placed $\frac{1}{2}$ " Iron Rod above. R.P. N.40. in C.F.P. 51.58' East, N.40. in Grace Post 61.60' SE.

"D" Located Iron pin: R.P. N40, T.P. NW. 55.50'; R.P. Steel post North 33.00'

"B" Wetlands survey crew, about 1971, set iron pin from measurements & angles of previous survey - found no evidence of original corner & old ties are gone: R.P. North end only. NW. 39.62'; R.P. South end only. SW. 41.80'; R.P. N40, SE. side T.P. NE. 56.50'; R.P. N40, SW. side R.P. SE. 57.68'