


MURRAY COUNTY.

Section 21

Township 105

Range 41

10798 McGill-Warner Co., Blank Book Manufacturers, St. Paul.



"B" Concrete Stone: R.P. Tack in Cor fence post N.W. 462'; R.P.

Tack in Cor. fence post SW 432';

"I" Concrete Stone: R.P. Tack in Cor. fence post west 332'; R.P. Tack in Blazed fence post N.W. 512'; F.A. March 1934

~~"B" Located and monument 13" below grade, Placed 1/2" rebar above:~~

~~R.P., N&C, Cor. Post N.W. 41.08; R.P., N&C, Cor. Post N.E. 45.00; R.P.~~

~~N&C, Cor. Post SW 48.90'~~

"I" Located Cor. Stone 15" below grade, Placed 1/2" rebar above. R.P.

~~chisled "x" on only end SW 62.69; R.P. chisled "x" on only end~~

~~SE 63.09'~~

"I" Placed 18" Conc. Mono. 4" below Gravel surface. ^{Sept, 75}

R.P. Chisled "x" on & Colu. End S.E. 46.96. Chisled "x" on & Colu. End S.W. 48.09

"B" Placed 18" Conc. Mono. 3" below Gravel surface. ^{Sept, 75}

R.P. N&C in P.P. S.W. 58.17 Nails in trap Road W. 100'-200'-300'

20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35