


# MURRAY COUNTY.

Section 23  
10798 McGill-Warner Co., Blank Book Manufacturers, St. Paul.

Township 108

Range 40



"B" Stone Tack in Cor fence post N.W. 37°; Tack in Cor fence post NE 38°

"I" Stone Tack in tel pole SE 34° stone on fence line East 7' from East shoulder.  
F.A. March 1934.

"H" Stone R.P. Tack in Blazed fence Cor S.W. 45°; R.P. Tack in Blazed fence Cor. N.W. 46°

"G" Stone R.P. Tack in Blazed cor post south 33°; R.P. Tack in gate post NE 41°

1936

"B" concrete stone R.P. X on south end of culvert 30.6

R.P. X north end of culvert 29.5' culvert in driveway East.

"I" concrete stone Hub East 50 Hub S.E. 50.0

"B" R.P. Tack in Cor fence post west on line 34.6'

R.P. Tack in Cor fence post NE 45°

"I" concrete stone R.P. Tack in Tel pole East 32.1'

R.P. Tack in Light pole S.W. 35.2'

"G" 1945 "B" R.P. South edge of culvert S.W. 31.2' R.P. Tack in cor fence post Hub 43° R.P. Tack in tel pole SE 41°

- 22
- 23
- 24
- 25
- 26
- 27
- 28
- 29
- 30
- 31
- 32
- 33
- 34
- 35
- 36