


MURRAY COUNTY.

Section 31
 10798 McGill-Warner Co., Blank Book Manufacturers, St. Paul.

Township 107

Range 41



June 20-1925

- "A"
- "B" Stone SE cor bridge 350 on line F 140 W - F cor. 424
- SE F cor. 575 NE "Placed Rock" R.P. Tack in cor. post North 32°
 (Found cedar post)
- "C" (1936) F.A. March R.P. Tack in Blazed fence post SW 348
- "D"
- "E"
- "F"
- "G"
- "H" T.W.P. Cor. Concrete fence post 345 NW. F. Cor. 37 SE
- "I" cor 383 S.W. F cor. 36 NE
- "I" found old cor. stake 73 stones concrete fence post
 West 219
- Feb 7-1934
- "D" Concrete stone R.P. Tack in cor fence post east
 774 R.P. Tack in cor fence post NW 44
- "E" concrete stone R.P. Tack in hub at bottom
 of steel post NE 406; Tack in hub at bottom
 of steel post SE 434; R.P. Tack in cor fence post
 West 332
- "F" concrete stone R.P. Tack in Lil pole NW 544
 R.P. Tack in Lil pole NE 57 - F.A. March

1968

- E. Iron Pin R.P. N+C T.P.
 NW - 93.50' R.P. N+C P.P.
 SE - 91.25'
- D. Iron Rod. R.P. "x" on NE
 cor School house SE - 69.80'
 R.P. N+C P.P. NE - 58.90'
 R.P. N+C T.P. NW - 68.05'


30
 31
 32
 33
 34
 35

SURVEY No. _____

Section 31

Town 107

Range 41



FIELD NOTES.

June 20, 1925

A Stone SE cor. Bridge 35.0 on line F 145 W - F 10.42.4 SE Feet. 51.5 NE

B
C
D
E
F
G
H Trip cor. Concrete line post 34.5 NW. F 10.39 SE. F 10.38 SW. Feet. 36 NE

I Found old cor. post at 2 stone Concrete E post 215 west

Feb 7, 1934
 "D" Concrete Stone R.P. Tack in cor fence post East 33 1/2'; R.P. Tack in cor fence post N.W. 44 1/2'.
 "E" Concrete Stone R.P. Tack in Hub At Bottom of Steel post N.E. 40 1/2'; Tack in Hub At Bottom of Steel post S.E. 43 1/2'; R.P. Tack in cor fence west 33 1/2'.
 "F" Concrete Stone R.P. Tack in Tel pole N.W. 54 1/2'; R.P. Tack in Tel pole N.E. 57 1/2'

J. A. March