

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

East Quarter Corner of Section 1, Township 107, Range 40, 5TH P.M.

STATE OF MINNESOTA, County of Murray

At the corner location shown on the sketch:

On 11/2/2025 found a 5/8" iron with an unreadable cap.

left monument as found, lowered monument, removed monument (explain)

On _____ placed a _____

SKETCH OF REFERENCE TIES



● MONUMENTS FOUND

NE CORNER
SEC. 1-107-40



OCCUPATION LINE


Murray County
Coordinate System NAD83 (1996)
N: 192498.204
E: 548369.857

SE CORNER
SEC. 1-107-40

WGS84
LAT: 44°06'05.8630"
LON: -95°34'57.1789"

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision


Daniel L. Bueltel
License No. 43844

1/16/2026
DATE

MURRAY COUNTY RECORDER


JAN 20 2026

Statement of Evidence

East Quarter Corner Section 1, T107N, R40W of the 5th P.M.

In 1861 J.W. Myers surveyed the original township lines.

September 1861, L. Brockmann did the original township subdivision.

On November 2, 2025 Bueltel-Moseng Land Surveying found a $\frac{5}{8}$ " iron with an unreadable cap midway and on line between the section corners. The iron fell at the intersection of the existing fence running north-south and the occupation line running east. Accepted the iron as the corner.