

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

East Quarter _____ Corner of Section 36, Township 107, Range 40, 5TH P.M.

STATE OF MINNESOTA, County of MURRAY


At the corner location shown on the sketch:

On 7/10/2025 found a 5/8" iron with seal #11943
DATE

left monument as found, lowered monument, removed monument (explain)

On _____ placed a _____
DATE

SKETCH OF REFERENCE TIES



Murray County
Coordinate System NAD83 (1996)
N: 166090.000
E: 548378.482

SE CORNER
SEC. 36-107-40

WGS84
LAT: 44°01'45.0929"
LON: -95°34'57.8683"

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Daniel L. Bueltel
License No. 43844

2/2/2026
DATE

MURRAY COUNTY RECORDER

FEB 06 2026

Statement of Evidence

East Quarter Corner Section 36, T107N, R40W of the 5th P.M.

In June of 1861 J.W. Myers surveyed the township lines.

In July of 1861, L. Brockmann subdivided the township.

On June 29, 1932 section 36 survey record shows found old corner placed a concrete marker.

December 28, 1989 Highway Department records show a concrete monument 24" below grade placed a 1-1/4" iron pipe with surveyors seal on top.

In September 2020 Westwood Professional Services found an iron with cap LS 11943 approximately 2.5ft east of the road center line and in line with E/W fence lines.

On July 10, 2025 Bueltel-Moseng Land Surveying found a $\frac{5}{8}$ " iron with seal #11943, probed along side and hit the concrete monument below, accepted the iron as the monument.