

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 5, Township 105, Range 39, 5TH P.M.

STATE OF MINNESOTA, County of MURRAY


At the corner location shown on the sketch:

On _____ found a _____
DATE

left monument as found, lowered monument, removed monument (explain)

On 10/8/2025 placed a 3" survey spike with seal 43844
DATE

SKETCH OF REFERENCE TIES




Murray County
Coordinate System NAD83 (1996)
N: 131749.840
E: 559031.416

NAIL AND SEAL
IN POWER POLE

WGS84
LAT: 43°56'05.7332"
LON: -95°32'33.3454"

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.



Daniel L. Bueltel
License No. 43844

1/14/2026
DATE

MURRAY COUNTY RECORDER



JAN 20 2026

Statement of Evidence

NORTHEAST CORNER SECTION 5, T105N, R39W OF THE 5th P.M.

In September of 1858 W.J. Neely surveyed the south township boundary.

In July of 1861 J.W. Myers surveyed the North, East, and West township boundary lines.

In August of 1861 Wellman & Smoot subdivided the township.

August 11, 1926, old survey notes a stone monument found.

Murray County Highway Department grading plans from 1961 show a stone was found at the corner.

County records from 1978 note corner was excavated to locate stone but found nothing. Notes that the stone could have been removed during 1972 regrade that has a 2' sub cut.

March 6, 2025, Bueltel-Moseng Land Surveying searched intersection for corner and found nothing. Re-established corner using stationing and deflection angles from 1961 highway plans between the southeast corner of 5-105-39 and the northeast corner of 32-106-39. Position fell in center of intersection. Using this method placed corner in center of intersection. Placed P.K. nail.

October 8, 2025, Bueltel-Moseng Land Surveying placed a 3" survey spike with seal 43844 over P.K. nail after overlay.