

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


# 23 MEANDER Corner of Section 25, Township 107 N., Range 39 W., 5<sup>th</sup> P.M.

STATE OF MINNESOTA, County of MURRAY

At the corner location shown on the sketch:

- On \_\_\_\_\_ found a \_\_\_\_\_  
DATE
- left monument as found,  lowered monument,  removed monument (explain)
- On \_\_\_\_\_ placed a \_\_\_\_\_  
DATE

## SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

LRP 11-6-85  
G-1181

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Lowell R. Pomeroy 11-7-85  
SIGNATURE DATE

Registration No. 17005

Land Surveyor,  Professional Engineer

County Surveyor,  County Engineer

OFFICE OF THE COUNTY RECORDER  
County of \_\_\_\_\_

I hereby certify that this document was filed in the Co. Recorders office at \_\_\_\_\_ .M. on the \_\_\_\_\_ day of \_\_\_\_\_ A.D., 19 \_\_\_\_\_

County Recorder \_\_\_\_\_  
By \_\_\_\_\_, Deputy  
DOCUMENT NO. \_\_\_\_\_

Meander Corner #23 of Section 25, Township 107 North, Range 39 West

This corner was originally established by the U. S. General Land Office survey in 1861. The government notes show corner marked with a wood post set in mound of earth with pits and trench dug around the mound. Also deposited charcoal and planted plum seeds northeast and southwest.

In March 1985, the DNR Bureau of Engineering contacted the following for corner information:

- Murray County Offices of the Recorder and Highway Engineer
- Mn/Dot Office in St. Paul
- U.S. Dept. of the Interior, Fish and Wildlife Office in Minneapolis
- Land Surveying Firms:
  - Sioux Engineering of Windom
  - Martin Land Surveying of Worthington
  - Madsen Land Surveyors of Fairmont

No resurvey information was obtained for this corner.

In March 1985, the DNR Bureau of Engineering traversed to the area of the corner and searched for, but did not find any evidence of the corner. Computed a temporary position for this corner on the easterly extension of a line from the northwest corner of Section 25 through the north quarter corner of Section 25, 1141.80 feet (GLO distance). Searched at the temporary position but found nothing, entire area is a floating bog.

Accept the temporary position as the location for the corner.

Traverse information is available from the DNR Bureau of Engineering.

167hab/missu4