	Index No.
CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
EAST 1/4 Corner of Section 5, Township 105, Range 42, 5TH P.M.	
STATE OF MINNESOTA, County ofMURRAY	
At the corner location shown on the sketch :	
☑ On <u>3/16/2006</u> found <u>STONE</u> , 1.75' LONG x 0.90' THICK.	
On 3/16/2006 set 5/8" REBAR WITH CAP: RLS 44563, BENEATH	
STONE IN SLOPE OF GROUND.	
Sketch of reference ties	
POWER POLE W/ NAIL & BOTTLE CAP ON SE SIDE Ø N87'56'29"W, 5327.99'	31.7' AT W SIDE OF POST
Statement of evidence relative to this corner location is on back page	
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. 6/29/06 Thomas V. Let Date	OFFICE OF THE COUNTY RECORDER County of

County Recorder

DOCUMENT NO ..

Registration No. ___

🛮 Land Surveyor, 🗌 Professional Engineer

☐ County Surveyor, ☐ County Engineer

STATEMENT OF EVIDENCE:

EAST 1/4 CORNER, SECTION 5, T. 105 N., R. 42 W.,

MURRAY COUNTY, MINNESOTA

1861 D.W. Wellman & S.S. Smoot, US. Deputy Surveyors, monumented corner.

? DATE Murray Co., found stone.

Ties: 53.8' to tck in blazed willow stump;

52.2' to tack in blazed willow stump, 4' south.

? Date Murray Co., found stone.

Ties: E-32.0' to tack in corner of fence posts;

30.4' to tack in mail box post;

NE-38.1' to edge of steel post.

09/1974 Murray Co., found concrete monument, 3" below sod, in slope of

ground.

Ties: E-31.65' to nail & cap in corner of fence posts;

NW-69.53' to nail & cap in power pole.

3/16/2006 Ulteig Engineers, Inc., Survey Crew, Brian Payne Party Chief

found a 1.75' long X 0.9' thick stone in the slope of the ground. Set 5/8" rebar with cap: RLS 44563, beneath stone & set stone

on top of rebar.

Ties: NW-69.5' to nail & cap on SE face of power pole;

E-31.7' to nail & bottle cap at base of fence post, on the west

face of said post.

N-2604.68' to NE corner, Section 5;

W-5327.99' to West 1/4 corner, Section 5.