Corners to be Indexed Section Township Range Corner NW 105 105 43 $N\frac{1}{4}$ 1 W1/4 105 43 1 105 43 C1/4 1 SW 1 105 43 I hereby certify that this survey, plan, or report was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the state of Minnesota. Signature Joshua M. Stern - LS 46169 (reserved for recording data) CERTIFICATE OF LOCATION OF GOVERNMENT CORNERS 105 43 Range Land Survey Monuments situated in Section West of the Township Fifth Principal Meridian, Murray County, State of Minnesota. Statement of Evidence for these corners can be found on the back of this page. Found Monument from former survey O Placed "46169 46171" Capped Iron Monument N¼ Corner S 89°47'29" E N 89°38'25" W 1" Iron Pipe **NW Corner** 2640.49 2632.20 Concrete **NE Corner** Monument 1" P.K. Nail -Index #A-25 S 1°10'19" W 2584.12 S 89°24'50" E N 89°22'23" W W1/4 Corner 2658.08 2666.10 E1/4 Corner 3/4" Rehar Capped Iron Rod C1/4 Corner Îndex #C-25 I" Iron Pipe **SW Corner** 11/2" Iron Pipe Note: No large excavation was done at this corner position as it is located within the road right of way.

STATEMENT OF EVIDENCE

Section 1, T105N-R43W

| 1866 | Original Government Land Office Survey |
|------------------|--|
| 1905 | Murray County Section Corner Records. |
| 1906 | Murray County Section Corner Records. |
| 1971 | Murray County Section Corner Records |
| 1975 | Murray County Section Corner Records |
| 1993 | Murray County Section Corner Records |
| 1999-2009 | LS 13593 Certificates of Survey |
| 2012-2019 | LS 43844 Certificates of Survey. |
| 2021 | Testimony taken by LS 50875. |
| 2021 NW Corner | Joshua M. Stern, LS 46169, while doing work for The Nature Conservancy, found a concrete monument 6" below the surface marked with an "x". This monument was verified by testimony taken by LS 50875, which stated a concrete monument was set after the county dug for the section corner in 1975. Stern accepted the monument as the best available evidence of the Section Corner position. |
| 2021 N1/4 Corner | Joshua M. Stern, LS 46169, while doing work for The Nature Conservancy, found a 1" iron pipe 10" below the road surface. The iron pipe matched distances with prior surveys and Stern accepted the monument as the best available evidence of the Section Corner position. |
| 2021 W1/4 Corner | Joshua M. Stern, LS 46169, while doing work for The Nature Conservancy, found ¾" rebar in the slough. The rebar matched distances with prior surveys and Stern accepted the monument as the best available evidence of the Section Corner position. |
| | |

2021 C1/4 Corner Joshua M. Stern, LS 46169, while doing work for The Nature Conservancy, found a 1" iron

2021 SW Corner Joshua M. Stern, LS 46169, while doing work for The Nature Conservancy, found a 11/2" iron

& E.-W. 1/4 lines"

pipe 10" below the surface. The iron pipe matched distances with prior surveys and as stated on a 2007 LS 13593 Certificate of Survey, "This found Mon. has been used as the center of Sec 1 in several previous surveys. This corner was established by Rieke-Carroll-Mueller Assoc. from ties. (The found iron pipe is 0.95 North & 0.98 West of true intersection of N.-S.

pipe 3" below the surface. The iron pipe matched distances with prior surveys and Stern accepted the monument as the best available evidence of the Section Corner position.