

Prepared by: Zieske Land Surveying, Inc. Address: Box 94, Windom, MN 56101 Phone: (507) 831-0100 UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE FOR Land survey monuments situated in Section 10 , Township 106 North, Range 43 West, of the Fifth Principal Murray ___ County, Minnesota.. N/A _____ in County Recorder's Office. Previously recorded in (Show reason for preparing this certificate, the evidence and detailed procedure used in establishing the corner position & monumentation found or placed.) MONUMENT DESCRIPTION AND REMARKS: On Nov. 20, 2006 we dug with a backhoe for W 1/4 Cor. ond found a 9" X 9" stone 8" deep with high point & accepted as corner. Set survey marker over top center of stone. At NW Cor. of Sec. there is a large box culvert crossing diagonally so didn't dig for corner. Set survey marker at Q Q of intersection for accepted corner and occupation line. Searched with backhoe for N 1/4 Cor. and did not find. Set 1" Iron Pipe with survey cap 23008 ot © Twp. Rd. in line with fence & occupation lines north & south as accepted location. At center of Sec. set 1" Iron Pipe with survey cap 23008 at intersection of opposite 1/4 corners as per PLS Instructions.

MURRAY COUNTY COORDINATES

PLAN-VIEW

N = 158384.87E = 440169.93





I hereby certify that this land surveying document was prepared and related survey work was performed by me or under my direct supervision and that I am a duly licensed Land Surveyor under the laws of the State of Minnesota.

Penny L. Zucka 12-19-06
Signature Date

Signatuse Perry Zieske License number 23008

Sheet 1 of 1

Corners to be Indexed

Corners	Section	Township	Range
NW	10	106	43
W 1/4	10	106	43
N 1/4	10	106	43
CTR.	10	106	43