
CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

North Quarter Corner of Section 13 , Township 108 , Range 41 5th P.M. STATE OF MINNESOTA, County of Murray.

Statement: Aug. 13, 1989 - Found a stone monument using Murray County Highway Department records. Placed a square Minnesota Department of Transportation Cast Iron Monument.



Statement of evidence relative to this corner location is on the back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision and that I am a duly Registered Land Surveyor under the laws of the State of Minnesota.

Duane A. Bonnema

Minnesota Registration No. 14895

OFFICE OF THE COUNTY RECORDER COUNTY OF MURRAY MAR 1 1 1991

I hereby certify that this document was filed in the County Recorder's office at .M. on the day of___ A.D., 19

County Recorder

Deputy

DOCUMENT NO.

North Quarter Cor. Sec. 13 T108N-R41W

Statement:

September 1861 Original Government Land Office Surveyor L. G. M.

Fletcher records in his field notes, "Built mound with trench pits, charred stake per instructions."

1934+ The Murray County Highway Engineer's Office records

in the County Surveyor's Record Book "stone" and then

they note witness ties to the corner.

April 17, 1979 The Murray County Highway Engineer's Office notes that

they found a field stone 21 inches below grade. They

also noted witness ties to the corner.

Aug. 31, 1989 Duane A. Bonnema, LS Reg. No. 14895, found a 3/4 inch

x 8 inch long re-rod at the subgrade level of the road. An 8 inch x 12 inch x 12 inch stone was found 3 feet below the road surface. Natural ground was found to be also 3 feet below the road surface. A square Minnesota

Department of Transportation Iron Monument with an aluminum

cap was placed at the road surface.