

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

North Quarter Corner of Section **14** , Township **108** , Range **41** 5th P.M.
STATE OF MINNESOTA, County of Murray.

Statement: Aug. 16, 1989 - Found 3 field stones at various depths. The bottom stone had remains of lath on 3 sides. Placed a Mn/DOT Cast Iron Monument.

SKETCH OF REFERENCE TIES



⊥ TOWNSHIP ROAD (1' North)



N1/4 Cor. Sec. 14

Statement of evidence relative to this corner location is on the back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision and that I am a duly Registered Land Surveyor under the laws of the State of Minnesota.


Duane A. Bonnema


Nov 6, 1989
Date

Minnesota Registration No. 14895

OFFICE OF THE COUNTY RECORDER
COUNTY OF MURRAY **NOV 15 1989**

I hereby certify that this document was filed in the County Recorder's office at ____ M. on the ____ day of _____ A.D., 19 ____

County Recorder



By _____, Deputy

DOCUMENT NO. _____

North Quarter Cor. Sec. 14 T108N-R41W

Statement:

September 1861 Original Government Land Office Surveyor L. G. M. Fletcher records in his field notes, " built mound with trench pts and charred stakes, per instructions."

Aug. 16, 1989 Duane A. Bonnema, L.S. Reg. No. 14895, found a 5 inch x 9 inch x 9 inch field stone 2 feet below the road surface. At a depth of 2.5 feet a 6 inch x 7 inch x 9 inch field stone was found. At a depth of 3 feet an 8 inch x 10 inch x 19 inch field stone was found with remains of a wooden lath on the East, South, and North sides. Original topsoil appeared to be at a depth of 2.5 feet below the road surface. The hole was dug to a depth of 4.5 feet and no additional evidence was found. A Minnesota Department of Transportation Cast Iron Monument was placed at the road surface.