

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


North Quarter Corner of Section **15** , Township **107** , Range **41** 5th P.M.
STATE OF MINNESOTA, County of Murray.

Statement: Aug. 9, 1989 - Found a field stone beneath a capped (Bell 16098) 3/4 inch iron pipe. Placed a Minnesota Department of Transportation cast iron monument at the corner.



SKETCH OF REFERENCE TIES

N1/4 Cor. Sec. 15



Statement of evidence relative to this corner location is on the back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision and that I am a duly Registered Land Surveyor under the laws of the State of Minnesota.


Duane A. Bonnema

Nov 6, 1989
Date

Minnesota Registration No. 14895

OFFICE OF THE COUNTY RECORDER
COUNTY OF MURRAY **NOV 15 1989**

I hereby certify that this document was filed in the County Recorder's office at ___M. on the ___ day of _____ A.D., 19__

County Recorder 

By _____, Deputy

DOCUMENT NO. _____

North Quarter Cor. Sec. 15 T107N-R41W

Statement:

- August 1861* *Original Government Land Office Survey or L. G. M. Fletcher records in his field notes, "Built mound with trench pits, charred stake, per instructions."*
- July 6, 1901* *J. W. Woolstencroft, County Surveyor, records in the County Surveyor's Record Book, page 138, "Cement Corner with wire" at this corner. He also shows that he measured to the Corner while doing survey work in Section 10.*
- Aug. 9, 1989* *Duane A. Bonnema, LS Reg. No. 14895, found a field stone below a capped (BELL LS 16098) 3/4 inch iron pipe. This stone and iron pipe are very close to the midpoint between the section corners 1/2 mile East and West.
A Minnesota Department of Transportation Cast Iron Monument was placed at the position of the 3/4 inch iron pipe.*