Index	No.	

CERTIFICATE OF LOCATION (	OF GOVERNMENT CORNER			
NORTH 1/4 Corner of Section 19. Township 105. Range 42, 5TH P.M.				
STATE OF MINNESOTA, County of	MURRAY			
At the corner location shown on the sketch :				
□ On 3/15/2006 found REBAR WITH UNREADABLE CAP, IN GRAVEL				
ROAD				
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)				
On set				
Sketch of reference ties				
	FIELD			
POWERPOLE W/NAILS "X" ON SIDE	ELECTRICAL			
WALLS OF SIDE	TRANSFORMER MEASURED FROM TOP SE CORNER BOX			
-Ŋ-	SE CONTRACT BOX			
200, 10				
31st STREET				
CDAVE COAD				
N89 25 44 W, 2511.01 589 22 19 E, 2640.91				
FOUND REBAR I UNREADABLE CAP	31st STREET			
	GRAVEL ROAD			
	© +			
FIELD	બ			
	FIELD .			
	N: 659,383.53			
	E: 2,114,793.07			
POWERPOLE	MN SOUTH ZONE, NAD 83			
W/NAILS "X" ON SIDE NOT TO SCALE				
	<b>7</b>			
Statement of evidence relative to this corner location is a	on back page			
I hereby certify that this document and the data	OFFICE OF THE COUNTY RECORDER			
contained herein was prepared by me or under	County of			
my direct supervision.	SEP 2 8 2006			
- 1100				
Thomas V: 2/1 4/20/06	I hereby certify that this document was filed in the Co. Recorders office atM. on the			
The Tops V. Zeff Date	day of ( A.D. , 20			
Registration No. 44563	County Recorder Xames V. X 5 hnson			
🛚 Land Surveyor, 📋 Professional Engineer	By, Deputy			
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO.			

## STATEMENT OF EVIDENCE:

NORTH 1/4 CORNER, SECTION 19, T. 105 N., R. 42 W.,

MURRAY COUNTY, MINNESOTA

D.W. Wellman & S.S. Smoot, US. Deputy Surveyors, monumented corner.

3/15/2006 Ulteig Engineers, Inc., Survey Crew, Brain Payne Party Chief, found a rebar with an unreadable cap, in the C/L of gravel road. Ties: NW-70.9' to nailed "X" on power pole;

NE-33.2' top, SE corner, electrical transformer box;

SE-84.3' to nailed "X" on power pole;

SE-84.3' to nailed "X" on power pole; E-2640.91' to NE corner, Section 19; W-2511.01' to NW corner, Section 19.