

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 22, Township 107, Range 39, 5TH P.M.

STATE OF MINNESOTA, County of MURRAY


At the corner location shown on the sketch:

On _____ found a _____
DATE

left monument as found, lowered monument, removed monument (explain)

On 11-21-2005 placed a 1" PIPE WITH SEAL #43844 MIDWAY AND ON LINE BETWEEN
DATE SECTION CORNERS.

SKETCH OF REFERENCE TIES



Nail and seal in power pole SSE 47.45'

Minnesota State Plane Coordinate
System Murray County Datum
NAD83 (1996)

N: 179367.070
E: 566786.287

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

James Buehler 12/13/05
SIGNATURE DATE

Registration No. 43844

Land Surveyor, Professional Engineer
 County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the Co. Recorders office at _____ .M on the _____ day of JAN 26 2006 A.D. 20____

County Recorder James V. Johnson
By _____, Deputy

DOCUMENT NO. _____

Statement of Evidence

On August 9 - September 2, 1861 Louis Brockman placed a pit and mound corner midway and on line.

On November 22, 2005 Bueltel-Moseng Land Surveying dug with a backhoe, nothing was found. A 1" pipe with seal #43844 was placed midway and on line between the section corners.