

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

North Quarter Corner of Section 25, Township 106, Range 43, 5th P.M.

STATE OF MINNESOTA, County of Murray


At the corner location shown on the sketch:

On \_\_\_\_\_ found a \_\_\_\_\_  
DATE

left monument as found,  lowered monument,  removed monument (explain)

On June 3, 1996 placed a 1" iron pipe w/seal #11943 (SEE BACK)  
DATE

### SKETCH OF REFERENCE TIES



Nail & seal in top of corner fence post 29.58'  
P.K. nail in corner of concrete on SW corner  
of bridge SSW 46.65'

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

John E. Moser 6-10-96  
SIGNATURE DATE

Registration No. 11943  
 Land Surveyor,  Professional Engineer

County Surveyor,  County Engineer

### OFFICE OF THE COUNTY RECORDER

County of \_\_\_\_\_

I hereby certify that this document was filed in the Co. Recorders office at \_\_\_\_\_ .M. on the \_\_\_\_\_ day of \_\_\_\_\_ A.D., 19 \_\_\_\_\_

County Recorder James V. Johnson  
By \_\_\_\_\_ JUN 19 1996, Deputy

DOCUMENT NO. \_\_\_\_\_

**Statement of Evidence:**

On June 3, 1996, Moseng Land Surveying, Inc. dug with a back hoe in the center line of road and in line with fence to the south. Found nothing. Set a 1" iron pipe w/seal #11943 in center line of road and in line with the fence to the south. The hole that was dug was 8'x7' and 4½' deep.