

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 36, Township 107N, Range 40W

5th Principal Meridian, State of Minnesota, County of MURRAY


At the corner location shown on the sketch:

On 8/26/2020 found a 6X6IN CONCRETE MONUMENT WITH SCRIBED "X" ON TOP DOWN 0.3FT
DATE

left monument as found lowered monument removed monument (explain)

On _____ placed a _____
DATE

SKETCH OF REFERENCE TIES



N.T.S.

Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature [Handwritten Signature]

Date 6/16/2021 License No. 45874

Title:

- Land Surveyor Professional Engineer
- County Surveyor County Engineer

OFFICE OF THE COUNTY RECORDER

County of Murray

I hereby certify that this document was filed in the Co.

Recorder's office at _____ M. on the _____ day of _____ A.D. 20 _____

County Recorder [Handwritten Signature]
by JUN 22 2021, Deputy

DOCUMENT NO. _____

JASON LATZKE
Minnesota License No. 45874

Statement of Evidence:

North quarter Corner of Section 36, Township 107 North, Range 40 West, 5th Principal Meridian, Murray County, Minnesota.

JUNE 29, 1932 - SURVEY RECORD FOR SECTION 36 SHOWS A SET CONCRETE MONUMENT.

UNDATED - HWY DEPT. RECORDS SHOW A CONCRETE MONUMENT 3" BELOW GRADE. N&C CORNER POST SOUTH 31.85; N&C BRACE POST NW 35.34. N&C PP SW 49.07.

SEPTEMBER 2020 - WESTWOOD PROFESSIONAL SERVICES SEARCHED AND FOUND CONCRETE MONUMENT WITH SCRIBED X ON TOP AND ALSO FOUND 1 TIE FROM HWY DEPT. RECORDS WHICH FIT WELL. ACCEPTED THE FOUND MONUMENT AND SET ADDITIONAL TIES.

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.