

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 04, Township 107N, Range 39W

5th Principal Meridian, State of Minnesota, County of MURRAY


At the corner location shown on the sketch:

On 11/03/2020 found a 6x6" CONCRETE MONUMENT WITH "X" SCRIBED ON TOP. 0.8FT BELOW GRADE.

left monument as found lowered monument removed monument (explain)

On 12/16/2020 placed a RAILROAD SPIKE ABOVE CONCRETE MONUMENT

SKETCH OF REFERENCE TIES



N.T.S.

Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature [Handwritten Signature]

Date 6/16/2021 License No. 45874

Title:

- Land Surveyor
- Professional Engineer
- County Surveyor
- County Engineer

OFFICE OF THE COUNTY RECORDER

County of Murray

I hereby certify that this document was filed in the Co.

Recorder's office at _____ M. on the _____ day of _____ A.D. 20

County Recorder Karen Brown

by JUN 22 2021, Deputy

DOCUMENT NO. _____

Statement of Evidence:

North Quarter Corner of Section 06, Township 107 North, Range 39 West, 5th Principal Meridian, Murray County, Minnesota.

No GLO Notes.

1940 *Survey record for Section 4 shows a concrete stone at the corner.*

Tack in cor. post N 34.1ft

Tack in fence post NW 49.4ft

Undated, Survey record for Section 33 notes a witness corner East 3 chains and shows a distance to both the Southwest and Southeast corners at 2646.0ft.

2020 *December, Westwood Professional Services excavated with a backhoe and found a concrete monument down approximately 1ft. I set a railroad spike just under road grade.*

Analysis of the recovered data, field evidence and survey measurements, indicates that the monument found is the correct perpetuation of this corner. For additional information concerning this corner please contact Westwood Professional Services.