

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 2, Township 106, Range 40, 5TH P.M.

STATE OF MINNESOTA, County of MURRAY


At the corner location shown on the sketch:

On _____ found a _____
DATE

left monument as found, lowered monument, removed monument (explain)

On 07-29-2011 placed a 1" pipe with seal #43844.
DATE

SKETCH OF REFERENCE TIES



Minnesota State Plane Coordinate
System Murray County Datum
NAD83 (1996)
N: 163473.034
E: 543144.734

Nail and survey marker in utility pole NE 43.72'
Nail and survey marker in utility pole NW 32.18'

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

David B. Smith 1/23/12
SIGNATURE DATE

Registration No. 43844

Land Surveyor, Professional Engineer
 County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER
County of _____

I hereby certify that this document was filed in the Co. Recorders office at _____ .M on the _____ day of JAN 25 2012 A.D. 20____

County Recorder *James V. Johnson*
By _____, Deputy

DOCUMENT NO. _____

Statement of Evidence

In 1861, J. W. Myers did the original survey of the township lines.

On the September 28, 1926, the corners location was established.

On April 22, 1930, a stone was found at the corner, a new stone was set over the old one.

On July 29, 2011, Bueltel-Moseng Land Surveying dug with a backhoe. We found nothing. We set a 1" pipe with seal #43844 in the center of the intersection.