CERTIFICATE OF LOCATION OF GOVERNMENT CORNER  Northeast Corner of Section 26 , Township 106 , Range 43 , t5thP.M.	
STATE OF MINNESOTA, County of Murray	
At the corner location shown on the sketch:	
Onfound a	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
1" iron pipo t/2001 #110/2 (SEE PACY)	
On June 3, 199 placed a 1 11011 pipe w/seal #11943 (SEE BACK)	
SKETCH OF REFERENCE TIES	
SKETCH OF REFERENCE TIES	
,	
-	
•	
75.53'	52.86' 52.64
Nail & seal in power pole SW 75.53'  Nail & seal in power pole SE 52.86'  Nail & seal in power pole seSE 52.64'	
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.    Mosery L-10-96	OFFICE OF THE COUNTY RECORDER  County of
☐ County Surveyor. ☐ County Engineer	DOCUMENT NO.

## Statement of Evidence:

On June 3, 1996. Moseng Land Surveying, Inc., dug with a back hoe in the center of intersection and found nothing. The hole was 6'x7' and 5' deep. Set a 1" iron pipe w/seal #11943 by occupational lines.