Index NoV-25
CERTIFICATE OF LOCATION OF GOVERNMENT CORNER
NORTHEAST Corner of Section 36 Township 108 N Range 41 W
5th Principal Meridian, State of Minnesota, County ofMURRAY
At the corner location shown on the sketch:
On 6/10/2008 found a 10" X 11" GRANITE STONE WITH A POINTED TOP, DOWN 2.0'
■ left manument as found □ lowered monument. □ removed monument (explain)
left monument as loans,
On6/10/2008 Placed a 3/4" X 12" REBAR WITH PLASTIC CAP STAMPED
"MN DNR LS 17003", DOWN 0.5', OVER STONE
NOTE: MONU IS
ON Q OF EAST-WEST ROAD
「」 4' WEST OF © ROAD NORTH 」
191st STREET
R41W
MURRAY COUNTY
COORDINATE SYSTEM NAD 1983 1996 ADJ.
N = 200448.889 GOOD TIES ARE NOT AVAILABLE
E = 516614.545
Statement of evidence for this corner location is on back of this page. SPK00220.00.00.01
I certify that this document was researched and prepared by me or under my direct supervision.
SIGNATURE License Number 17003
Title: 📕 Land Surveyor 🗆 Professional Engineer 🗆 Caunty Surveyor 🗀 County Engineer

v-25

Northeast Corner of Section 36, Township 108 North, Range 41 West, Page 1 of 2

The DNR Division of Lands and Minerals contacted the following for survey information:

Minnesota Secretary of State's Office Murray County Recorder's Office Murray County Highway Engineer's Office Bueltel-Moseng Land Surveying of Marshall Zieske Land Surveying Inc. of Windom Madsen Land Surveying Inc. of Fairmont

Pellinen Land Surveying of Hutchinson

- 1861 U.S. General Land Office notes, obtained from the Secretary of State's Office, show the corner marked with a wood post and a charred stake in a mound of earth with trench and pits as per instructions.
- 1913 September 15, Surveyor's Record Book, obtained from the County Highway Engineer's Office, contains a survey of Section 25 by J.H. Woolstencroft. Survey shows the following at corner:

 stone in grade
- 1913 September 15, Murray County Highway Department section corner information website, shows a stone in grade at corner.
- 1936 A Survey Map by the National Park Service that shows Sections 5 and 6, T107N, R40W, Sections 1 and 2, T107N, R41W, and Sections 35 and 36, T108N, R41W, in the possession of the DNR Division of Lands and Minerals, shows that a stone was found at the corner. The corner is shown:

at the intersection of the centerline of roads north and west

1972 September, Surveyor's Record Book, obtained from the County Highway Engineer's Office, shows a stone and wood stake with steel bolt on top at corner with the following ties:

nail & disc in T.C.T, 52.47 feet, northwest

nail & disc in side of 6" tree, 38.57 feet, southwest

nail & disc in power pole, 50.85 feet, southeast

nail & disc in northwest side of tree, 82.00 feet, west-southwest

- The plat of PLEASANT VIEW ACRES SUBDIVISION in Sections 30,31,36 by J.S. Richmond, LS 2129, obtained from the County Recorder's Office, shows a 1 ½ inch bold inplace at the section corner.
- June 10, the DNR Division of Lands and Minerals hired a backhoe, operated by Butch Barton of B & L Excavation, Inc. of Currie, to dig for evidence of a monument at the corner. A 12 inch long by ¾ inch diameter bolt with a 1 ½ inch square top was found down 1 foot. Further excavating revealed a 10 inch by 11 inch granite stone with a pointed top down 2.0 feet and 0.53 of a foot southwest of the found bold.

Searched for but found no evidence of the record ties.

Northeast Corner of Section 36, Township 108 North, Range 41 West, Page 2 of 2

Analysis of the above information led the DNR Division of Lands and Minerals to conclude that the found stone marks the location of the corner. A 3/4 inch diameter by 24 inch long rebar was set down 2.0 feet on the south side of the found stone. Also, set a 3/4 inch diameter by 12 inch long rebar with a plastic cap stamped "MN DNR LS 17003" over the found stone. The found bolt was discarded.