CERTIFICATE OF LOCATIO	N OF GOVERNMENT CORNER		
NORTHEAST Corner of Section 7, Township 107 N, Range 39 W, 5 th. P.M. STATE OF MINNESOTA, County of MURRAY At the corner location shown on the sketch On 10-9-91 found a 12" x 19" x 19" GRANITE STONE, WITH PIECES OF			
		LATH, DOWN 2.5' left monument as found, D lowered monument, D removed monument (explain)	
		•	REBAR WITH ALUMINUM CAP STAMPED
			, OVER STONE , DOWN 0.4
SKETCH OF	REFERENCE TIES		
DNR NAIL & DISC WSW SIDE WOOD CORNER FENCE POST, UP 4 N 51°W 57.15'	DNR NAIL & DISC SOUTH SIDE POWER POLE UP 4' N 43 E 43.66'		
NOTE: MONUMENT IS I'WEST OF & N-S ROAD ON & E-W ROAD	S 46°E 48.82' DNR NAIL & DISC SW SIDE POWER POLE UP 4'		
983 MURRAY COUNTY OORDINATE SYSTEM = 189,936.889 = 553,485.679 BEARINGS OBSERVED WITH COMPASS			
Statement of evidence relative to this corner location is on back of page J.B.M. 11-19-91 WMA 00065.00.00.01			
i hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.	OFFICE OF THE COUNTY RECORDER County of		
NUCL W. MISSING 12-2-91 Section No. 17003 Land Surveyor, D Professional Engineer County Surveyor, D County Engineer	County Recorder ames V. kohnson		

Northeast Corner of Section 7, Township 107 North, Range 39 West

The DNR Bureau of Engineering contacted the following for survey information:

Minnesota Secretary of State's Office Murray County Recorder's Office Murray County Highway Engineer's Office

- 1861 U.S. General Land Office notes obtained from the Secretary of State's Office show the corner marked with pits and mound.
- 1991 October, DNR Bureau of Engineering hired a backhoe to dig for evidence of a monument at corner. Found a 12" by 19" by 19" granite stone down 2.5 feet with pieces of lath next to it. The stone was found to be: on the center line of an east-west road

 1 foot west of the center line of a north-south road
 2635.84 feet from the north quarter corner of Section 7

2673.88 feet from the east quarter corner of Section 7

Analysis of the above information led the DNR Bureau of Engineering to conclude that the found granite stone marks the location of the corner.