Index No.	
CORNER	
<u>43W, 5TH</u> P.M.	
ADABLE CAP, IN THE	

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER					
WEST 1/4 Corner of Section 18, Township 106N, Range 43W, 5TH P.M.					
STATE OF MINNESOTA, County ofMURRAY					
At the corner location shown on the sketch :					
☑ On 3/22/2006 found A REBAR WITH AN UNREADABLE CAP, IN THE					
C/L OF COUNTY LINE AVE, OPPOSITE A FENCE LINE RUNNING EAST.					
On set					
Sketch of reference ties					
	AVE.	AD			
	Y LINE 33'	GRAVEL ROAD	FIELD		
-N-	COUNTY LINE	GRA			
	7	J			
FIELD	2,06				
	NO1'12'06"E		N N		
APPROACH	•	-	33.7' x		
	RE	CAPPED BAR	WOOD FENCE POST W/PK NAIL ON SIDE		
FIELD		5.02			
		o"w, 2645.02			
	ш				
N: 694,521.33	COUNTY LINE AV	SO1'12'0 GRAVEL ROAD	FIELD		
E: 2,081,417.89 MN SOUTH ZONE, NAD 83	J YTN	SO			
NOT TO SCALE	000	5			
Statement of evidence relative to this corner location is on back page					
Statement of evidence relative to this corner location is on back page					
I hereby certify that this document and the data contained herein was prepared by me or under			CE OF THE COUNTY RECORDER y of		
my direct supervision.			SEP 2 8 2006		
Thems 1. Zell 5/22/06		I hereby certify that this document was filed in the Co. Recorders office otM. on the			
Thomas V Zeff Date day of A.D., 20					
Registration No. 44563 County Recorder Comuse Vi Sohns					
County Surveyor, County Engineer			DOCUMENT NO.		

STATEMENT OF EVIDENCE:

WEST 1/4 CORNER, SECTION 18, T. 106 N., R. 43 W.,

MURRAY COUNTY, MINNESOTA

1861 J.W. Myers, US. Deputy Surveyor, monumented west range line.

10/20/1901 Murray Co. placed a stone, 10"X14"X20", in grade, on the corner; no ties.

3/22/2006 Ulteig Engineers, Inc., Survey Crew, Dennis Lavallie Party Chief, found a rebar with an unreadable cap, in the C/L of the gravel road, opposite a fence line running east.

Ties: E-33.7' to PK nail in wood fence post; N-2644.93' to NW corner, Section 18; S-2645.02' to SW corner, Section 18.