Index No.
OVERNMENT CORNER
105, Range <u>42, 5TH</u> P.M.
nument, removed monument (explain) WITH CAP: RLS 44563, NCE LINE RUNNING EAST.
ce ties
FIELDxxx
CHISELED "X" ON TOP EAST END 24" RCP
AD 83
page
ICE OF THE COUNTY RECORDER
SEP 2.8.2006

CERTIFICATE OF LOCATION OF G WEST 1/4 Corner of Section 33, Township STATE OF MINNESOTA, County of _____MU At the corner location shown on the sketch : found _____ left monument as found, lowered mo On 3/19/2006 set 5/8" REBAR X OPPOSITE FE Sketch of referen SET 5/8" REBAR W/CAP: RLS 44563 CHISELED "X" ON TOP WEST END 24" RCP FIELD N: 645,909.07 E:2,122,425.09 MN SOUTH ZONE, NA NOT TO SCALE Statement of evidence relative to this corner location is on back OFF I hereby certify that this document and the data contained herein was prepared by me or under Coun my direct supervision. I hereby certify that this document was filed in the Co. Recorders office at ______ .M. on the /24/06 .M. on the A.D. , 20 day of 44563 Registration No. County Recorder, Professional Engineer , Deputy DOCUMENT NO. County Surveyor, County Engineer

STATEMENT OF EVIDENCE:

WEST 1/4 CORNER, SECTION 33, T. 105 N., R. 42 W., MURRAY ___ COUNTY, MINNESOTA

1861 D.W. Wellman & S.S. Smoot, US. Deputy Surveyors, monumented

corner.

Murray Co., placed concrete stone on corner. Ties: W-34.8' to tack in corner post; NW-61.1' to tack in seconds fence post. ? Date

Murray Co., found concrete monument, 3" below grade. ? Date

Ties: W-46.3' to nail & cap in 1st post; E-36.3' to nail & cap in corner post; NE-40.6' to 1st steel post.

3/09/2006 Ulteig Engineers, Inc., Survey Crew, Brain Payne Party Chief,

fence line going east & nothing in road.

Set a 5/8" rebar with cap: RLS 44563, opposite fence line.

Ties: SW-53.4' to chiseled "X", top, W end, 24" C.M.P.;

SE-49.1' to chiseled "X", top, E end, 24" C.M.P.;

N-2651.03' to NW corner, Section 33; S-2621.90' to SW corner, Section 33.