

FIELD NOTES

OF THE SURVEY OF THE

SUBDIVISION AND MEANDER LINES

OF

Township No. 106 North, Range No. 43 West

OF THE

5^d Principal Meridian,

IN THE STATE OF MINNESOTA,

AS SURVEYED BY

J. M. Bishop

U. S. DEPUTY SURVEYOR,

Under his Contract No.

Dated May 26 1866 190

Survey commenced Sept 8 1866

Survey completed Sept 15 1866

T 106 or R 43 W.

Meander notes of a lake in
sections 12 + 13 Town 106 Range 43.

The meander corner between
fractional sections 13 + 18 in
the East boundary of the
Township + on the South
shore of the Lake being
extinct I restore and reestablish
is as follows:

Commencing at the 1/4 section
corner, in the East boundary
of the Town + between sections
13 + 18. I run north bet.

Secs 13 + 18 Var. 11.50 E.

27.93 To the South shore of the
Lake; where I set a post
with pit ^{Restablished} for meander
corner, on the north shore of
the Lake; in the East
boundary of the Town +
between fractional sections

T 106 or R 48 W. 13

12 + 7, being extinct, I restore
+ re-establish it as follows.

Commencing at the $\frac{1}{4}$ section
corner in the East boundary
of the Town + between
fractional sections 7 + 12 -
I run South between sections
7 + 12.

Var. $11^{\circ} 50' E$.

15.08 To the North shore of the
Lake; where I set a post
with pit + c. for re-established
meander corner:

Commencing at the re-
established meander corner
between sections 13 + 18 on
South Shore of the Lake
I meander in section 13
as follows.

Var $11^{\circ} 30' E$.

N. 46° W 7.00 chs.

14

S 106 m R 48 W

N 24° E 7.00 chs.

N 66 W 4.26 .. to the
meander corner on West shore
and between sections 12+13.

Thence in section 12.

N 54° W 7.00 chs

N 82° W 9.00 ..

N 62½° W 11.00 ..

North 5.00 ..

N 40° E 8.00 ..

N 70° E 14.00 ..

S 82½° E 13.00 .. to the
meander corner on north shore
and between sections 12+7This lake has gravelly beach
no timber about it. Water
is good but slightly
alkaline.

September 10, 1866