

SURVEYOR'S RECORD

Section 14

Township 106

Range 42

B		C	D
I		A	E
H		G	F

March 26, 1913

"G" Located 2x2 Hub/nail 1.8' Below oil mat. Placed steel pin in 3" bituminous overlay July 5, 1913
R.P. steel pipe cor. post of sub station Painted Red S.E. 45⁸⁵; R.P. N&C, PP, NW 57¹⁵;
R.P. N&C, PP, SW 59⁵²