

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

East Quarter Corner of Section 12, Township 107, Range 40, 5TH P.M.

STATE OF MINNESOTA, County of Murray


At the corner location shown on the sketch:

On 7/30/2025 found a 3/4" rebar with an aluminum capped iron
DATE stamped "DNR SURVEY MARKER".

left monument as found, lowered monument, removed monument (explain)

On _____ placed a _____
DATE

SKETCH OF REFERENCE TIES



Murray County
Coordinate System NAD83 (1996)
N: 187208.177
E: 548364.340

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Daniel L. Bueltel
License No. 43844

1/26/2026
DATE

MURRAY COUNTY RECORDER

JAN 20 2026

Statement of Evidence

East Quarter Corner Section 12, T107N, R40W of the 5th P.M.

In 1861 J.W. Myers surveyed the original township lines.

September 1861, L. Brockmann did the original township subdivision.

A corner certificate dated August 12, 1991 by Bruce W. Shepperd, L.S. 17003, notes he did not find anything at the corner. He computed the corner on line between the northeast corner of section 12 and the east quarter corner of section 13 and on the fence line running east-west.

County records dated January 29, 2008 shows that Zieske Land Surveying found a DNR survey monument.

On July 30, 2025 BuelteI-Moseng Land Surveying found a $\frac{3}{4}$ " rebar with an aluminum cap stamped "DNR SURVEY MARKER". Corner fell on the fence line running east-west, accepted the rebar as the corner.