

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

East Quarter Corner of Section 20, Township 107, Range 39, 5TH P.M.

STATE OF MINNESOTA, County of Murray


At the corner location shown on the sketch:

On 5/7/2025 found a 1/2" rebar in the center line of the road and in line with  
DATE  
fence line to the west and occupation line to the east.

left monument as found,  lowered monument,  removed monument (explain)

On \_\_\_\_\_ placed a \_\_\_\_\_  
DATE

### SKETCH OF REFERENCE TIES



Murray County  
 Coordinate System NAD83 (1996)  
 N: 176658.219  
 E: 558862.638

WGS84  
 LAT: 44°03'29.1938"  
 LON: -95°32'33.9847"

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision

Daniel L. Bueltel  
 License No. 43844

1/27/2026  
DATE

**MURRAY COUNTY RECORDER**

*Karen Brown*

FEB 02 2026

## Statement of Evidence

East Quarter corner Section 20, T107N, R39W of the 5th P.M.

In October of 1857, J.W. Myers surveyed the east township line.

In July of 1861 J.W. Myers surveyed the north, south, and west township lines.

In September of 1861, L. Brockmann subdivided the township.

A survey record dated April 14, 1974 notes they dug a 6'x6'x7' deep hole with a backhoe and found nothing.

A survey in Section 20 by Perry Zieske, L.S. 23008, in October of 2000 shows a iron monument at the corner.

A survey in Section 21 by Perry Zieske, L.S. 23008, in August of 2006 shows a survey spike over an iron monument at the corner.

In September of 2020 Westwood Professional Services searched and found a No. 4 rebar at the corner and set ties.

On May 7, 2025 Bueltel-Moseng Land Surveying searched the area and found a  $\frac{1}{2}$ " rebar at the corner. The corner fell in the center line of the road and in line with fence running west and the occupation line running east. All ties are good.