

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


East Quarter Corner of Section 25, Township 107, Range 40, 5TH P.M.

STATE OF MINNESOTA, County of Murray

At the corner location shown on the sketch:

- On 7/10/2025 found a 5/8" iron with broken cap.
DATE
- left monument as found, lowered monument, removed monument (explain)
- On _____ placed a _____
DATE

SKETCH OF REFERENCE TIES




Murray County
 Coordinate System NAD83 (1996)
 N: 171378.490
 E: 548378.729

SE CORNER
 SEC. 25-107-40

WGS84
 LAT: 44°02'37.3148"
 LON: -95°34'57.7033"

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.


 Daniel L. Bueltel
 License No. 43844
 DATE 1/16/2026

MURRAY COUNTY RECORDER

Karen Brown

JAN 20 2026

Statement of Evidence

East Quarter Corner Section 25, T107N, R40W of the 5th P.M.

In 1861 J.W. Myers surveyed the original township lines.

September 1861, L. Brockmann did the original township subdivision.

In September of 2020 Westwood Professional Services found a No. 5 rebar at the corner.

On July 10, 2025 BuelteI-Moseng Land Surveying found a $\frac{5}{8}$ " iron with a broken cap at the corner. Accepted the iron as the corner.