

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

East Quarter Corner of Section 26, Township 105, Range 40, 5TH P.M.

STATE OF MINNESOTA, County of Murray


At the corner location shown on the sketch:

☒ On 5/11/2026 found a iron with a broken yellow cap 3"± below the road surface.
DATE

☒ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☒ On 7/31/2026 placed a 3" survey spike with seal #43844 over top of found iron.
DATE


SKETCH OF REFERENCE TIES



Murray County
Coordinate System NAD83 (1996 Adj.)
N: 107922.559
E: 543312.857

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.




Daniel L. Bueltel
License No. 43844

7/31/2026
DATE

RECORDING INFORMATION

AUG 05 2026



MURRAY COUNTY RECORDER

Statement of Evidence

East Quarter Corner Section 26, T105N, R40W of the 5th P.M.

August, 1858 - W.J. Neely surveyed the south boundary line of the township.

June, 1861 - J.W. Myers surveyed the north, east, and west boundary lines of the township.

July, 1861 - D.W. Wellman & S.S. Smoot subdivided the township.

July, 30, 2015 - County records note a iron stake with broken cap 3" below the road surface at the corner.

May 11, 2026 - Bueltel-Moseng Land Surveying found a iron with a broken yellow cap 3"± below the road surface.

July 31, 2026 - Bueltel-Moseng Land Surveying set a 3" survey spike with seal #43844 over top of the found iron after the county over lay project.