

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

_____ NORTHEAST _____ Corner of Section 2, Township 105 N, Range 41 W, 5 TH P.M.

STATE OF MINNESOTA, County of MURRAY


At the corner location shown on the sketch:

On 06/23/2017 found a REBAR NEAR CENTERLINE OF ROAD EAST-WEST IN LINE FENCE LINE
DATE

NORTH.

left monument as found, lowered monument removed monument (explain)

On _____ place a _____
DATE



MURRAY COUNTY
 COORDINATE
 (2011 ADJUSTMENT)

N:131724.449
 E:511382.514

Statement of evidence and reference ties relative to the corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

[Signature]
SIGNATURE

8-24-17
DATE

License No. 49020

Land Surveyor, Professional Engineer
 County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the Co Recorders office at _____ .M. on the _____ day of _____ A.D. 20

County Recorder _____

By _____, Deputy

DOCUMENT NO. _____

Statement of Evidence:

1861 – Corner established during survey of township exterior boundarys

1957 – MNDNR Assumed position for corner to be at the centerline of road east–west in line with fence lines north–south.

1970 – MNDNR found and used previously set I.P..

1973 – MNDNR found and used previously set I.P.

2017 – Jibben Surveying found rebar near the centerline of road east–west in line with fence line to the north. Used rebar as corner monument.

SECTION 2
TOWNSHIP 105 NORTH, RANGE 41 WEST

