

JUL 3 1 2026

Statement of Evidence

Northeast Corner of Section 26, T105N, R41W of the 5th P.M.

September 1858 - W.J. Neely surveyed the south township boundary.

July, 1861 - J.W. Myers surveyed the east, north, and west township boundary lines.

August&September 1861 - Wellman & Smoot subdivided the township.

Undated - County survey record of Section 26 shows a concrete stone at the corner.

October 1967 - County survey record of Section 26 shows an iron pin in place at the corner.

September 24, 1984 - County records show a p.k. nail in place at the corner.

December 12, 2013 - Zieske Land Surveying found a p.k. nail at the corner.

May 26, 2026 - Bueltel-Moseng Land Surveying searched the area and found a $\frac{3}{4}$ " iron 1.5'± below the surface of the road. After review of grading plans from the county it was determined that the concrete monument was removed during the road regrade. The found $\frac{3}{4}$ " iron is the best evidence of the corner.

July 7, 2026 - Bueltel-Moseng Land Surveying set a 3" survey spike with seal #43844 at the location of the $\frac{3}{4}$ " iron after the county overlay project.