

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 7, Township 106, Range 40, 5TH P.M.

STATE OF MINNESOTA, County of MURRAY


At the corner location shown on the sketch:

On _____ found a _____
DATE

left monument as found, lowered monument, removed monument (explain)

On 4/7/15 placed a survey spike with seal #43844
DATE

SKETCH OF REFERENCE TIES



Minnesota State Plane Coordinate
System Murray County Datum
NAD83 (1996)

N: 158112.431
E: 521955.056

Found chiseled "X" in culvert NW 44.95'
Found chiseled "X" in culvert NE 41.72'
Nail and bottle cap in utility pole SW 58.37'

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

[Signature] 3/2/16
SIGNATURE DATE

Registration No. 43844

Land Surveyor, Professional Engineer
 County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER

County of MURRAY

I hereby certify that this document was filed in the Co. Recorders office at 11:00 A.M. on the 18TH day of OCTOBER A.D. 20 16

County Recorder Evelyn C. Larson

By _____, Deputy

DOCUMENT NO. _____

Statement of Evidence

In 1861, D.W. Wellman and S.S. Smoot did the original subdivision of the township.

On November 2, 1899, J.W. Woolstencroft recorded a stone at the corner. It is 33 feet south and 30 feet west of fence.

On April 21, 1969, Murray County Highway Department found a field stone and set a concrete monument with a steel pin at the corner. Tied out corner with chiseled "X" on culvert ends to the northeast and northwest, and nail and bottle cap in utility pole to the southwest.

On April 7, 2015, Bueltel-Moseng Land Surveying set a survey spike with seal #43844 by using chiseled "X" on culvert ends northeast and northwest of corner, according to the 1969 survey. It fit the tie to the utility pole to the southwest.