CERTIFICATE OF LOCATION OF GOVERNMENT CORNER
NORTHEASTCorner of Section7,Township107,Range39,5THP.M.
STATE OF MINNESOTA, County ofMURRAY
At the corner location shown on the sketch:
On 6/7/2024 found a 3/4" iron with DNR stamped cap.
☐ Ieft monument as found, ☐ lowered monument, ☐ removed monument (explain)
Onplaced a
SKETCH OF REFERENCE TIES
MONUMENTS FOUND BROKEN SCALE S 89'01'06" W 2635.93' S 89'34'28" E 2657.59' NW COR. NE1/4 SEC. 8-107-39
Murray County Coordinate System NAD83 (1996) N: 189936.932 E: 553484.649 Murray County Coordinate System NAD83 (1996) SECOR. NE1/4 SEC. 7-107-39 LAT:44*05'40.4529" LON:-95*33'47.1769"
Statement of evidence relative to this corner location is on back of page.
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. MAR 13 2025 MAR 13 2025 Mar Brown Daniel L. Bueltel License No. 43844 MUNAY COUNTY RECORDER

Statement of Evidence

NORTHEAST CORNER SECTION 7, T107N, R39W of the 5th P.M.

In July of 1861, J.W. Myers layed out the original township lines.

In September of 1861, L. Brockmann did the original township subdivision.

In October 1991 DNR Bureau of Engineering dug and found a 12" by 19" by 19" granite stone down 2.5 feet with lath next to it. They then placed a $\frac{3}{4}$ " iron with an aluminum cap stamped "DNR SURVEY MARKER" over top of the stone.

County records show on October 28, 2008, an iron monument was located at the corner by Zieske Land Surveying.

County records show on May 26, 2016, an iron pin with a DNR survey cap was located at the corner.

On June 7, 2024, Bueltel-Moseng Land Surveying found a $\frac{3}{4}$ " iron with an aluminum cap stamped "DNR SURVEY MARKER" at the corners location.